

OCEAN CITY: INSTALLED 1980

<u>Riser No.</u>	<u>Material Changes Since Original Installation</u>
C.O.	None
1	Replaced w/HDPE (11/04 per SER-25-04). Replaced top 8' Section w/HDPE (9/06 per Quote). Replaced top 8' Section again w/HDPE (6/08 following inspection per RFP-06-08). Replaced top 8' section again w/HDPE (12/10 per WW-22-10). Small ¼" gap below HDPE riser section per 2012 inspection (5/12). All connections tight per 2013 inspection (7/13)
2	None
3	None
4	None
5	None
6	None
7	None
8	None
9	None
10	None
11	None
12	None
13	None
14	None
15	None
16	None
17	None
18	None
19	None
20	None
21	None
22	None
23	None
24	None
25	Replaced w/HDPE (8/16 per Quote by CDS), Replaced with HDPE (3/17 per WW-41-16).
26	Replaced with HDPE (6/18 per WW-27-17-REBID)
27	None
28	None
29	None
30	None
31	None
32	None
33	None
34	None
35	None
36	None
37	None
38	None
39	None

OCEAN CITY: INSTALLED 1980

<u>Riser No.</u>	<u>Material Changes Since Original Installation</u>
40	None
41	None
42	None
43	None
44	None
45	None
46	None
47	None
48	None
49	None
50	None
51	None
52	None
53	None
54	None
55	None
56	None
57	None
58	None
59	None
60	None
61	Replaced both sections w/FRP (11/04 per SER-25-04). Replaced top Section w/ FRP, 5' long (7/14 per RFP-08-14 Repair Work). Replaced top section w/ HDPE (3/17 per WW-41-16)
C.O.	None