

WILDWOOD NORTH: INSTALLED 1988

| <u>Riser No.</u> | <u>Material Changes Since Original Construction</u> |
|-------------------------|--|
| 1N | None |
| 2N | None |
| 3N | None |
| 4N | Replaced w/ HDPE (9/07 per WW-23-07) |
| 5N | None |
| 6N | None |
| 7N | None |
| 8N | None |
| 9N | None |
| 10N | None |
| 11N | None |
| 12N | Missing per 2017 inspection (6/17); Replaced w/HDPE (8/18 per WW-27-17-REBID) |
| 13N | None |
| 14N | None |
| 15N | None |
| 16N | None |
| 17N | None |
| 18N | None |
| 19N | None |
| 20N | None |
| 21N | None |
| 22N | None |
| 23N | Replaced missing riser w/base blind flange (12/99 per Inspection CO.); Replaced w/FRP (11/04 per SER-25-04) |
| 24N | Replaced missing riser w/base blind flange (12/99 per Inspection CO.); Replaced w/HDPE (11/04 per SER-25-04) |
| 25N | Replaced w/HDPE (12/10 per WW-22-10) |
| 26N | None |
| 27N | None |
| 28N | None |
| 29N | None |
| 30N | None |
| 31N | None |
| 32N | None |
| 33N | Replaced w/HDPE (11/04 per SER-25-04); Replaced top section w/HDPE (7/21 per WW-19-21) |
| 34N | None |
| 35N | None |
| 36N | None - Leaning about 5 degrees south per 2011 inspection (6/11) |
| 37N | None - Leaning about 5 degrees south per 2019 inspection (6/19) |

